

CENTRAL

ce
10-12-83
(2)

HAZARDOUS WASTE INSPECTION REPORT
Generators - Part A

Date of inspection 09-14-83 Time start 10:15 AM Time finish 10:40 AM
Name of inspector ARTHUR L. DIALL PIAZZA
Company, installation name HAMILTON TECHNOLOGY
Location 101 NORTH QUEEN STREET
County LANCASTER Municipality LANCASTER CITY
Identification number PAD 000800680
Name of responsible official KENNETH R. BERNHARDT
Title PRESIDENT
Mailing address P.O. BOX 4787 LANCASTER PA 17604
Area code and phone no. 717-299 2581
Name of person interviewed ROBIN E. THOMAS
Title MGR, CHEMISTRY LAB
Mailing address (if different from above) _____
Area code and phone no. _____

1. Current waste handling method:

- a. ☐ On-site ☐ treatment, ☐ storage, ☐ disposal
b. ☒ On-site ☐ use, ☐ reuse, ☐ recycle, ☒ reclaim
c. ☒ Off-site ☒ treatment, ☐ storage, ☒ disposal
d. ☒ Off-site ☐ use, ☐ reuse, ☐ recycle, ☒ reclaim

2. Amount of hazardous waste produced:

- a. _____ kg./mo.
b. _____ kg./yr.

OCT 11 1983

DIV. OF HAZARDOUS W.

3. Types of hazardous waste produced by Hazardous Waste Number:

D001, F001, F003, F005 FLAMMABLE, SOLVENTS & DISTILLATES
F007/9, D003, D006/7 TOXICANT PERMIT - BY-PRODUCT → F006 SLUDGE

4. Are hazardous wastes transported off-site by the generator? ☐ Yes ☒ No

BECKETT PRODUCTS PAD 003003844

HAZARDOUS WASTE INSPECTION REPORT
Generators - Part

1- NON-COMPLIANCE, 2-COMPLIANCE, 3-NOT APPLICABLE, 4-NOT DETERMINED

COMPLIANCE STATUS				REQUIREMENT	CHAPTER CITATION
1	2	3	4		
	X			Identification number	(c) (1)
	X			Hazardous waste shipments offered only to licensed transporters	(c) (4)
	X			Authorization received from TSD facility for wastes shipped off-site	(d)
	X			PA manifest used for intrastate shipments	(e) (1) (i)
		X		Disposer state manifest or EPA format manifest used for out-of-state shipments	(e) (1) (i)
	X			Manifests filled out properly and completely	(e) (1)
	X			Manifests routed properly and within time limits (24 hours)	(e) (2)
	X			Proper U.S. DOT shipping containers or packages	(f) (1) (i)
	X			Shipping containers marked and labeled according to U.S. DOT	(f) (1) (i)
	X			Containers of 110 gal. or less marked with required PA label	(f) (1) (i)
	X			Placards offered to transporter	(f) (2)
	X			Wastes accumulated on-site for less than 90 days	(g) (1)
	X			Wastes stored in proper containers and properly marked and labeled	(g) (1) (i)
	X			Containers managed in accordance with 75.265(g)	(g) (1) (i)
	X			Containers clearly marked with accumulation date and visible for inspection	(g) (1) (i)
	X			Records retained at designated location for 20 years.	(h)
	X			Quarterly reports submitted to the Department	(i)
	X			Exception reporting procedures followed	(j)
		X		Hazardous waste disposal plan, if required	(l)
	X			Spill reporting procedures followed	(m) (1)
	X			Preparedness, Prevention and Contingency Plan approved and implemented	(m) (5)
		X		Special requirements followed for international shipments	(o)

PAID 000800680 09-14-83

75.262

11/13/83

OCT 11 1983

DIV. OF HAZARDOUS WASTE

HAZARDOUS WASTE INSPECTION REPORT
TSD Facilities - Part A

CE 10-12-83

Date of inspection 09-14-83 Time start 10:10AM Time finish 11:20AM
Name of inspector ARTHUR L. DALLA PIAZZA
Company, installation name HAMILTON TECHNOLOGY INC.
Location 101 NORTH QUEEN STREET
County LANCASTER Municipality LANCASTER CITY
Identification number PAD 000 800 680
Name of responsible official KENNETH R. BERNHARDT
Title PRESIDENT
Mailing address PO BOX 4787 LANCASTER PA 17604
Area code and phone no. 717-299-2581
Name of person interviewed ROBIN E. THOMAS
Title MGR CHEM LAB
Mailing address (if different from above) ~
Area code and phone no. ~


Site characterization:

- a. ☒ Treatment - PERMIT-BY-RULE ☐ surface impoundments, ☒ chemical, ☒ physical, ☐ biological
b. ☒ Storage - ☒ containers, ☐ tanks, ☐ surface impoundments, ☐ waste piles
c. ☐ Disposal - ☐ land treatment, ☐ landfill, ☐ incineration, ☐ thermal treatment
d. ☐ Use, ☐ reuse, ☒ recycle, ☐ reclaim

Does the facility generate hazardous wastes? ☒ Yes ☐ No

Types of hazardous waste produced by Hazardous Waste Number:

SEE GENERATOR



Are hazardous wastes transported off-site by the facility? ☐ Yes ☒ No

SEWER DISCHARGE AFTER TREATMENT CITY OF LANCASTER


HAZARDOUS WASTE INSPECTION REPORT
Part C - Comments

Date of inspection 09-14-83 Identification number PAD 000800620
Company, Installation name HAMILTON TECHNOLOGY
County LANC. Municipality LANCASTER CITY

PERMIT - BY - ROLE DETERMINATION HAS BEEN ISSUED
FOR THE TREATMENT ACTIVITIES FOR THIS FACILITY. INSPECTION THIS
DAY REVEALED NO VIOLATIONS OF THE § 75.265(2)(17) REQUIREMENTS

THE AREA TO BE UTILIZED FOR HW STORAGE SHOULD
BE POSTED WITH THE REQUIRED SIGNS AS PER § 75.265(4)(3)
AS THIS AREA BECOMES ESTABLISHED.

INSPECTION THIS DAY REVEALED NO VIOLATIONS OF
§ 75.265(9) REQUIREMENTS FOR DRUM STORAGE.



This inspection report is official notification that a representative of the Department of Environmental Resources, Bureau of Solid Waste Management, inspected the above installation. The findings of this inspection are shown in this report. Any violations which were uncovered during the inspection are indicated. Violations may also be discovered upon examination of the results of laboratory analyses and review of Department records. Notification will be forthcoming, confirming any violations indicated herein and listing any additional violations.

Person Interviewed (signature) Robin Thomas Date 9-14-83
Inspector (signature) Arthur L Della Rocco Date 09-14-83